



# >TECHNICAL SUPPORT TECHNICAL BULLETIN

## IP Softphone 2050v2 Vista Compatibility Configuration - BCM

BULLETIN ID: 2008008997, Rev 1

PUBLISHED: 2008-08-07 STATUS: Active REGION: APAC

CALA EMEA GC NA

PRIORITY: Information TYPE: Bulletin

## **Background:**

A product issue has been identified with the IP Softphone 2050v2, which is the currently supported softclient for the Business Communication Manager (BCM) phone system. This product issue (CR Q01863946) results in impaired audio performance when the 2050v2 client is used on a PC running the Microsoft Vista operating system. This bulletin details the necessary configuration steps to prevent audio quality problems when using the IP Softphone 2050v2 on a Vista PC.


## Analysis:

The IP Softphone 2050v2 has been found to experience significant impairment of the audio channel when run on a PC using the Microsoft Vista operating system. In order to ensure clear audio when using the Softphone on a PC running Vista, follow the steps provided in RECOMMENDATIONS.


#### **Recommendations:**

The IP Softphone 2050v2 has been found to experience significant impairment of the audio channel when run on a PC using the Microsoft Vista operating system. In order to ensure clear audio when using the Softphone on a Vista machine, the following steps need to be taken.

1. From the options at the top of the 2050 client, select File, Settings.



2. From the settings list, select Audio.
Using the slidebar, increase the Quality setting to 4 or higher



Note that for the IP Softphone 2050v1.4 the same steps should be taken, but a third step is also required.

#### 3. IP Softphone 2050v1.4 ONLY

If using an IP Softphone 2050v1.4 on a Vista PC, after setting the audio quality to 4 or higher (step 2), QoS must be turned off on the PC itself.

Use the Vista Service Manager to disable QoS on the PC.

## **Required Actions:**

See RECOMMENDATIONS.

### **Attachments:**

There are no attachments for this bulletin

## **Products and Releases:**

The information in this bulletin is intended to be used with the following products and associated releases:

PRODUCT	RELEASE
BCM-BCM1000 Global	
BCM-BCM1000 N.A.	
BCM-BCM-BCM200 Global	
BCM-BCM200 N.A.	
BCM-BCM-BCM400 Global	
BCM-BCM-BCM400 N.A.	
BCM-BCM-BCM50 Global	
BCM-BCM50 N.A.	
BCM-BCM-BCM50 R2 Global	
BCM-BCM-BCM50 R2 N.A.	
BCM-BCM-BCM50 R3 Global	
BCM-BCM-BCM50 R3 N.A.	
BCM-BCM50a Global	
BCM-BCM50a N.A.	
BCM-BCM50a R2 Global	
BCM-BCM50a R2 N.A.	
BCM-BCM-BCM50a R3 Global	
BCM-BCM50a R3 N.A.	
BCM-BCM50b R2 Global	
BCM-BCM-BCM50b R3 Global	
BCM-BCM50ba R2 Global	
BCM-BCM50ba R3 Global	
BCM-BCM50be R2 Global	
BCM-BCM50be R3 Global	
BCM-BCM50e Global	
BCM-BCM50e N.A.	
BCM-BCM50e R2 Global	
BCM-BCM50e R2 N.A.	
BCM-BCM-BCM50e R3 Global	
BCM-BCM50e R3 N.A.	
Phones & Accessories-IP-IP Softphone 2050	

To view the most recent version of this bulletin, access technical documentation, search our knowledge base, or to contact a Technical Support Representative, please visit

REFERENCE: PRE-REQUIRED PATCH:

Nortel Technical Support on the web at: http://support.nortel.com/. You may also sign up to receive automatic email alerts when new bulletins are published.

PATCH ID:

Copyright 2007 Nortel Networks. All rights reserved. Information in this document is subject to change without notice. Nortel assumes no responsibility for any errors that may appear in this document. The information in this document is proprietary to Nortel Networks.

Nortel recommends any maintenance activities, such as those outlined in this bulletin, be completed during a local maintenance window.

Nortel, the Nortel logo, and the Globemark design are trademarks of Nortel Networks. All other trademarks are the property of their respective owners.