



Global Power Supply replacements available for Nortel IP Phones

BULLETIN ID: 2009009912, Rev 1
PUBLISHED: 2009-12-11
STATUS: Active
REGION: APAC
CALA
EMEA
GC
NA
PRIORITY: Information
TYPE: Bulletin

Background:

This Product Bulletin is to advise customers that a replacement global power supply is now available for any ongoing requirements for discontinued Nortel IP Phones. Customers looking for replacement power supplies for the previously supported 16VAC country specific power supplies for use with the IP Phone 2000 Series, including IP Phone 2001, IP Phone 2002, IP Phone 2004 models, can purchase the Nortel global power supply (NTYS17BAE6) and a standard country-specific IEC cable, as shown in the following list.

Analysis:

The Replacement part is: NTYS17BAE6 - Global power supply

One country specific standard IEC power cord is also required per global power supply.

- NTYS14AAE6 - Standard IEC Cable - North America
- NTTK16ABE6 - Standard IEC Cable - Europe
- NTTK17ABE6 - Standard IEC Cable - Switzerland
- NTTK18ABE6 - Standard IEC Cable - UK
- NTTK22ABE6 - Standard IEC Cable - Denmark
- NTTK26AAE6 - Standard IEC Cable - Japan
- A0814961 - Standard IEC Cable - Argentina
- NTTK15AA - Standard IEC Cable - Australia / New Zealand

This is the same global power supply used on the Nortel IP Phone 1100 Series and IP Phone 1200 Series models.

The following discontinued 16 VAC Power Adapters for the Nortel IP Phone 200x models including IP Phone 2001, 2002, 2004 have been replaced by the Global Power Supply and country-specific IEC cable noted above. The 16 VAC Power Adapters below were discontinued for use in year 2006.

- A0619627 - North America - Power Transformer
- A0656598 - Ireland / UK - Power Transformer
- A0619635 - Europe - Power Transformer
- A0647042 - Australia / NZ - Power Transformer

Recommendations:

For any ongoing requirements for replacement power supplies for the IP Phone 2000 Series, please use the replacement

codes listed in this bulletin.

Required Actions:

None

Attachments:

There are no attachments for this bulletin

Products and Releases:

The information in this bulletin is intended to be used with the following products and associated releases:

PRODUCT	RELEASE
Phones & Accessories-IP-IP Phone 2001	
Phones & Accessories-IP-IP Phone 2002	
Phones & Accessories-IP-IP Phone 2004	

To view the most recent version of this bulletin, access technical documentation, search our knowledge base, or to contact a Technical Support Representative, please visit Nortel Technical Support on the web at: <http://support.nortel.com/>. You may also sign up to receive automatic email alerts when new bulletins are published.

REFERENCE:
PRE-REQUIRED PATCH:
PATCH ID:

Copyright 2009 Nortel Networks. All rights reserved. Information in this document is subject to change without notice. Nortel assumes no responsibility for any errors that may appear in this document. The information in this document is proprietary to Nortel Networks.

Nortel recommends any maintenance activities, such as those outlined in this bulletin, be completed during a local maintenance window.

Nortel, the Nortel logo, and the Globemark design are trademarks of Nortel Networks. All other trademarks are the property of their respective owners.